

CityDiff Sample Report

Two-week imagery comparison and permit-record triage

Imagery interval: May 17, 2026 - May 31, 2026 (14 days)

SAMPLE REPORT DISCLAIMER

The OpenStreetMap basemap depicts a real geographic area. All finding pins, coordinates, imagery, parcel identifiers, permit records, dates, annotations, and findings are fictional and do not describe the mapped properties.

4

Imagery findings

1

Likely permit match

3


Staff review recommended

0

Records unavailable

Finding overview

Ordered by review priority



Finding 01

Detached backyard structure

Review priority: HIGH

STAFF REVIEW RECOMMENDED

Parcel ID: 218-041-017
Coordinates: 34.2220, -119.1950

Imagery confidence High	Parcel association High	Permit screen No match found
-----------------------------------	-----------------------------------	--

OLDER
 May 17, 2026
 NEWER
 May 31, 2026



Observed change

A detached roofed footprint is visible in the rear yard in the newer image and is not visible in the older image.

Permit-record screen

Records searched

Municipal Building & Safety records through Jun 02, 2026; parcel ID, work type, and 2025-2026 date range.

Permit record

No corresponding accessory-structure record was found in the available permit dataset.

Match basis

No matching permit record was available for scope comparison.

Suggested staff check

Confirm recent applications and determine whether the observed structure falls within local permit requirements.

NO PERMIT-STATUS DETERMINATION

Permit-record results reflect the listed source and data cutoff date.

Finding 02


Roofed side addition

Review priority: MEDIUM

STAFF REVIEW RECOMMENDED

Parcel ID: 218-041-021
Coordinates: 34.2180, -119.1664

Imagery confidence High	Parcel association Medium	Permit screen Potential match
-----------------------------------	-------------------------------------	---



Observed change

A roofed footprint is visible beside the central residence in the newer image where an open side yard was previously visible.

Permit-record screen

Records searched

Municipal Building & Safety records through Jun 02, 2026; parcel ID, address key, and open permits.

Permit record

BLD-25-0077 - interior remodel and window replacement; status: active.

Match basis

The parcel and timing overlap, but the available work description does not clearly include an exterior footprint addition.

Suggested staff check

Review the permit scope or plan set before deciding whether additional action is warranted.

NO PERMIT-STATUS DETERMINATION

Permit-record results reflect the listed source and data cutoff date.

Finding 03


Pool excavation in progress

Review priority: MEDIUM

STAFF REVIEW RECOMMENDED

Parcel ID: 218-042-006
Coordinates: 34.2090, -119.1772

Imagery confidence High	Parcel association High	Permit screen No match found
-----------------------------------	-----------------------------------	--



Observed change

A rectangular pool-shaped excavation, partial perimeter forming, and an adjacent spoil pile are visible in the rear yard in the newer image.

Permit-record screen

Records searched

Municipal Building & Safety records through Jun 02, 2026; parcel ID, address key, pool/spa work type, and 2025-2026 date range.

Permit record

No corresponding pool or spa permit record was found in the available permit dataset.

Match basis

No matching permit record was available for scope comparison.

Suggested staff check

Confirm recent applications and determine whether the excavation is associated with an active permit.

NO PERMIT-STATUS DETERMINATION

Permit-record results reflect the listed source and data cutoff date.

Finding 04

Active residential re-roofing

Review priority: LOW

LIKELY PERMIT MATCH - DEPRIORITIZED

Parcel ID: 218-042-014
 Coordinates: 34.2120, -119.1982

Imagery confidence
High

Parcel association
High

Permit screen
Strong candidate match



Observed change
 Part of the central roof appears stripped to orange-tan underlayment, with roofing materials visible in the newer image.

Permit-record screen

Records searched
 Municipal Building & Safety records through Jun 02, 2026; parcel ID, address key, work type, and issue date.
Permit record
 RERF-26-0142 - residential re-roof; issued May 22, 2026; status: active.
Match basis
 Same parcel, compatible work description, and overlapping imagery interval.

Suggested staff check
 No immediate action. Staff may confirm that the visible work is within the permit scope if desired.

CANDIDATE MATCH - SCOPE MAY REQUIRE CONFIRMATION

Permit-record results reflect the listed source and data cutoff date.